

Mask Set Errata

MSE912D60C_2L02H
Rev 0, 01/2003

Mask Set Errata for
68HC912D60C
Mask 2L02H



introduction

This errata provides information applicable to the following MCU mask set devices:

- 2L02H masks of the MC68HC912D60C

MCU Device Mask Set Identification

The mask set is identified by a four-character code consisting of a letter, two numerical digits, and a letter, for example F74B. Slight variations to the mask set identification code may result in an optional numerical digit preceding the standard four-character code, for example 0F74B.

MCU Device Date Codes

Device markings indicate the week of manufacture and the mask set used. The data is coded as four numerical digits where the first two digits indicate the year and the last two digits indicate the work week. The date code "9115" would indicate the 15th week of the year 1991.

MCU Device Part Number Prefixes

Some MCU samples and devices are marked with an SC, PC, ZC or XC prefix. An SC, PC or ZC prefix denotes special/custom device. An XC prefix denotes device is tested but is not fully characterized or qualified over the full range of normal manufacturing process variations. After full characterization and qualification, devices will be marked with the MC prefix.

MSE Published Date: 26 March 2003

Errata Summary

Errata number	Module affected	Description
AR_659	ATD	Abort in last ATDCLK of sequence does not restart
AR_593	CGM	Operation with 16MHz quartz crystals is not recommended
AR_650	CGM	XIRQ during last cycle of STOP instruction causes run away
AR_644	ECT	PA Overflow flag not set when event is concurrent with write of \$FFFF
AR_646	MSCAN	MSCAN extended ID rejected if stuff bit between ID16 and ID15

Abort in last ATDCLK of sequence does not restart

Errata Number: HC12_AR_659

Description

When writing ATDCTL4 and/or ATDCTL5 during an active conversion the write is considered an abort and restart. However, when writing during the last ATDCLK of a sequence, the current conversion is aborted, but a new conversion is not started. This occurs whether the sequence is 1 or 4 or 8 conversions. Since writes to ATDCTL4 start a conversion then it is possible for successive byte writes to ATDCTL4/5 to result in this problem. This would occur if an IRQ service related to another interrupt source occurs, separating the two byte writes, and the RTI of this returns delaying the second write to occur in the last ATDCLK.

Workaround

The first aspect of the solution is to use word writes to ATDCTL4/5. This eliminates the possibility of other IRQ sources causing delay between writes to ATDCTL4/5. This would be the only solution required when starting the first conversion. It would also be the only solution needed when SCAN=0 if all further conversion sequences are initiated from an ATD interrupt routine. In addition, this is the only solution needed if code, in general, does not abort ongoing conversions.

The second aspect to the solution regards cases that abort conversions. The easiest solution is to toggle the S8C bit. This effectively cleans up the abort and the second write to the ATDCTL5 will perform a successful restart. Bracket this toggle sequence with SEI and CLI to prevent the second write from occurring during a last ATDCLK of a sequence.

Another method is possible using dual writes to start a conversion with a minimum of one ATDCLK period between the writes. This effectively allows the first write to abort and flush by the next write which would start (or restart) the conversion. The second write also needs to occur before another sequence complete time elapses. This method should also be prefixed by a SEI and

followed by a CLI. This would prevent the case of other IRQ sources causing the same problem as well.

Operation with 16MHz quartz crystals is not recommended

Errata Number: HC12_AR_593

Description

Interaction of the resonator and microcontroller characteristics can result in a small proportion of applications failing to start up and stabilize correctly even though typical product combinations work well under test conditions. Resonator operation should be restricted to maximum 10 MHz

Workaround

1. Use 10 MHz (or slower) resonators and generate higher bus frequencies using the PLL module. Note: When using 10 MHz or slower resonators proper and robust operation of the oscillator circuit requires close attention to board layout to ensure correct gain margin and negative resistance margin. There is a well documented analysis technique performed to measure Negative Resistance Margin which indicates the margin for stable oscillation of the combined microcontroller and resonator. However, an alternative approach is to include gain margin analysis. Since a negative resistance margin optimization cannot include all process, temperature, and voltage variance of the microcontroller, it is possible that the components chosen for the optimum negative resistance point may not yield acceptable component values for gain margin. In this case a compromise between the negative resistance margin and gain margin is desired. However option 2 (below) may be necessary should this remain unachievable.
 - The EXTAL pin input accepts frequencies greater than 10 MHz. In this case, use of an external quartz oscillator module or other source of externally generated clocks at the desired frequency, up to the 16 MHz specification, will allow the MCU to function correctly.

XIRQ during last cycle of STOP instruction causes run away

Errata Number: HC12_AR_650

Description

If an XIRQ interrupt occurs during the execution of the STOP instruction with the control bit DLY=0 (located in the INTCR register), the CPU may not run the software code as designed.

Workaround

1. Set the delay control bit DLY=1 so that a delay will be imposed prior to coming out of STOP.

2. If using XIRQ with a stable external clock and DLY=0, contact Motorola Applications Department for a detailed workaround.

PA Overflow flag not set when event is concurrent with write of \$FFFF
Errata Number: HC12_AR_644
Description

When the value \$FFFF is written to PACA or PACB and, at the same time, an external clocking pulse is applied to the PAC, the pulse accumulator may overflow from \$FFFF to \$0000, but the pulse accumulator overflow flag [PAFLG,PBFLG] is not set. Same situation may happen with 8-bit pulse accumulators PAC1 and PAC3.

Workaround

The input capture function for the subject channel be enabled prior to writing a value to the PACA or PACB. Write to the pulse accumulator register. Then do one NOP (to allow the input capture to update the interrupt flag) followed by a read of the input capture interrupt flag to see if it set. If yes, a check must be made for a missing pulse accumulator event. Steps for software workaround to see if event happens while writing to PAC:

1. Enable Input Capture on same pin as the pulse accumulator (and same type of event).
2. Clear the appropriate CxF in the timer interrupt flag register.
3. Read PAC and store as "Old PAC".
4. Calculate desired PAC value and write it to the PAC.
5. Execute 1 NOP.
6. Read CxF in the timer interrupt flag register.

If flag is not set, done (no events happened while writing to the PAC).


If flag is set read PAC

If "Old PAC" = PAC, then update PAC (event happened while writing to PAC and the PAC did not capture it). Note, if the updated PAC value is \$00 jump to PACOV ISR.

If "Old PAC" does not equal PAC, does PAC = \$00 ?

If yes, jump to PACOV ISR.

If no, done (event happened while writing to the PAC and PAC captured it). Read CxF in the timer interrupt.



MSCAN extended ID rejected if stuff bit between ID16 and ID15

Errata Number: HC12_AR_646

Description

For 32-bit and 16-bit identifier acceptance modes, an extended ID CAN frame with a stuff bit between ID16 and ID15 can be erroneously rejected, depending on IDAR0, IDAR1, and IDMR1.

Extended IDs (ID28-ID0) which generate a stuff bit between ID16 and ID15:

IDAR0	IDAR1	IDAR2	IDAR3
*****	***1111x	xxxxxxxxx	xxxxxxxxx

where x = 0 or 1 (don't care)
* = pattern for ID28 to ID18 (see following).

Affected extended IDs (ID28 - ID18) patterns:

- a. xxxxxxxx01exceptions:0000000001
01111100001
xxx1000001 except 11111000001
- b. xxxxx100000exception:01111100000
- c. xxxx01111111exception:00000111111
- d. x01111110000
- e. 10000000000
- f. 11111111111
- g. 10000011111

When an affected ID is received, an incorrect value is compared to the 2nd byte of the filter (IDAR1 and IDAR5, plus IDAR3 and IDAR7 in 16-bit mode). This incorrect value is the shift register contents before ID15 is shifted in (i.e. right shifted by 1).

Workaround

If the problematic IDs cannot be avoided, the workaround is to mask certain bits with IDMR1 (and IDMR5, plus IDMR3 and IDMR7 in 16-bit mode).

Example 1: to receive the message IDs
xxxx xxxx x011 111x xxxx xxxx xxxx xxxx
IDMR1 etc. must be 111x xxx1, i.e. ID20,19,18,15 must be masked.

Example 2: to receive the message IDs
xxxx 0111 1111 111x xxxx xxxx xxxx xxxx
IDMR1 etc. must be 1xxx xxx1, i.e. ID20 and ID15 must be masked.

In general, using IDMR1 etc. 1111 xxx1, i.e. masking ID20,19,18,SRR,15, hides the problem.

HOW TO REACH US:

USA/EUROPE/LOCATIONS NOT LISTED:

Motorola Literature Distribution;
P.O. Box 5405, Denver, Colorado 80217
1-303-675-2140 or 1-800-441-2447

JAPAN:

Motorola Japan Ltd.; SPS, Technical Information Center,
3-20-1, Minami-Azabu Minato-ku, Tokyo 106-8573 Japan
81-3-3440-3569

ASIA/PACIFIC:

Motorola Semiconductors H.K. Ltd.;
Silicon Harbour Centre, 2 Dai King Street,
Tai Po Industrial Estate, Tai Po, N.T., Hong Kong
852-26668334

TECHNICAL INFORMATION CENTER:

1-800-521-6274

HOME PAGE:

<http://motorola.com/semiconductors>

Information in this document is provided solely to enable system and software implementers to use Motorola products. There are no express or implied copyright licenses granted hereunder to design or fabricate any integrated circuits or integrated circuits based on the information in this document.

Motorola reserves the right to make changes without further notice to any products herein. Motorola makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Motorola assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters which may be provided in Motorola data sheets and/or specifications can and do vary in different applications and actual performance may vary over time. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. Motorola does not convey any license under its patent rights nor the rights of others. Motorola products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the Motorola product could create a situation where personal injury or death may occur. Should Buyer purchase or use Motorola products for any such unintended or unauthorized application, Buyer shall indemnify and hold Motorola and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Motorola was negligent regarding the design or manufacture of the part.



Motorola and the Stylized M Logo are registered in the U.S. Patent and Trademark Office. digital dna is a trademark of Motorola, Inc. All other product or service names are the property of their respective owners. Motorola, Inc. is an Equal Opportunity/Affirmative Action Employer.

© Motorola, Inc. 2003

Additional mask set erratas can be found on the World Wide Web at <http://motorola.com/semiconductors>.