ENIGMA USER MANUAL

FORD S-MAX 2011 9512

DASHBOARD PHOTO:

REQUIRED CABLE(s): C12





FOLLOW THIS INSTRUCTION STEP BY STEP:

- 1. Remove the dashboard and open it carefully.
- 2. Remove the back side of the dash to get to the main board.
- 3. Solder C12 cables as shown on PHOTO 1.
- 4. Make sure that the connection you made is secure.
- 5. Use EDITOR to save memory backup data.
- 6. Press the READ KM button and check if the value shown on the screen is correct.
- 7. Now you can use the CHANGE KM function.



PHOTO 1: Solder C12 cables according to the colors like shown on the photos above.



ENIGMA USER MANUAL

FORD S-MAX 2011 9512

LEGAL DISCLAIMER:

DIAGCAR ELECTRONICS S.L. does not take any legal responsibility of illegal use of any information stored in this document. Copying, distributing or taking any action in reliance with the content of this information is strictly prohibited.

