# Rover 75 DASH

Use C7 cable, open back plastic cover, now locate points in the main board like in photo below and solder cable leads as it shows to us:

USUALLY OLD VALUE WILL NOT BE RECOGNIZED, ALTHOUGH NEW VALUE WILL SHOWN AFTER RECALIBRATION!!!

TO MAKE A GOOD JOB REMEMBER TO **MODIFY LCM** AND **EWS**