VW LT-35

Use specific cable **C32**, remove dash from car, connect plug to dash like we can see on next photo and run program: