FORD FIESTA 2008 9512



USE CABLE C12, REMOVE BACK PLASTIC COVER, LOOK FOR POINT ON MAIN BOARD AND SOLDER CABLE LEADS ACCORDING TO COLOURS AS SHOWN ON BELOW PHOTO:

