


BMW 3 SERIES E46 LCM DIRECT HC12



USE CABLE C12,
REMOVE MODULE FROM
CAR, OPEN COMPLETELY
IT, WHEN WE HAVE
BOARD ON OUR HANDS,
FIRST CONNECT
POWER LEADS:



AND THEN CONNECT
OR SOLDER CABLE
LEADS ACCORDING
TO POINTS SHOWN
INTO PHOTO:

