


BMW 3 SERIES E46 LCM DIRECT HCS12



LOCATION

USE CABLE C12,
REMOVE MODULE FROM
CAR, OPEN COMPLETELY
IT, WHEN WE HAVE
BOARD ON OUR HANDS,
FIRST CONNECT
POWER LEADS:



AND THEN CONNECT OR
SOLDER CABLE LEADS
ACCORDING TO POINTS
SHOWN INTO PHOTO:

