BMW X3 LCM DIRECT 2007



USE CABLE C12, REMOVE MODULE FROM CAR, OPEN COMPLETELY IT, WHEN WE HAVE BOARD ON OUR HANDS, FIRST CONNECT POWER LEADS:

AND THEN CONNECT OR SOLDER CABLE LEAD ACCORDING TO POINT SHOWN IN THE SIDE PHOTO:

