

ROVER 45



USE CABLE C4, REMOVE DASH FROM CAR, OPEN DASH, AND PLEASE MAKE IT CAREFULLY. TAKE OFF NOW ONLY SPEDOMETER, IT IS THE SCREEN ONE, NOW LOCATE EPROM 93C46 MEMORY, AND CLIP IT CHECKING PIN 1 AS SHOWN OF PHOTO BELOW:

