

NISSAN PRIMERA TO 1999



USE CABLE C4, REMOVE FRONT PLASTIC COVER, TAKE OFF SPEEDOMETER, ONLY FIXING WITH 4 SCREWS. THEN LOCATE EPROM MEMORY 93C46, **THAT WE MUST DESOLDER**, CLIP IT CHECKING PIN 1 AND RESOLDER AS SHOWN OF PHOTO BELOW:

