


FORD MUSTANG FROM 2005 SECURED**DASH PHOTO:****REQUIRED CABLE(s):
C45 + A6****FOLLOW THIS INSTRUCTION STEP BY STEP:**

1. Remove the dashboard and open it carefully.
2. Remove the back side of the dash to get to the main board.
3. Solder C45 cables as shown on PHOTO 1.
4. Solder C45 cables as shown on PHOTO 2.
- ! Remember to connect A6 adapter !**
5. Make sure that the connection you made is secure.
6. Use EDITOR to save memory backup data.
7. Press the READ KM button and check if the value shown on the screen is correct.
8. Now you can use the CHANGE KM function.

**PHOTO 1:** Solder C45 cables as shown on the photo above.

FOR MORE INFORMATION

Call **0034 983 359 787** or visit www.enigmatool.com

DIAGCARELECTRONICS S.L. Ebanistería 1A, 47610 Zaratán, Spain

FORD MUSTANG FROM 2005 SECURED




PHOTO 2: Solder C45 cables as shown on the photo above.

LEGAL DISCLAIMER:

DIAGCAR ELECTRONICS S.L. does not take any legal responsibility of illegal use of any information stored in this document. Copying, distributing or taking any action in reliance with the content of this information is strictly prohibited.

FOR MORE INFORMATION

Call **0034 983 359 787** or visit www.enigmatool.com

DIAGCAR ELECTRONICS S.L. Ebanistería 1A, 47610 Zaratán, Spain