

JAGUAR X-TYPE FROM 2004



USE CABLE C12 OR HCS12, REMOVE BACK SIDE OF DASH, THEN CONNECT OR SOLDER POWER LEADS AND CABLE LEADS ACORDING TO COLOURS AS SHOWN OF BELOW PHOTO:

