

KIA CARNIVAL



USE C5 CABLE, REMOVE SPEDOMETER MODULE, IT IS THE SCREEN ONE, THEN WE CAN SEE THE 93C46 EPROM, AND WITH THE PHOTO BELOW WE CAN CLIP MEMORY OR WE CAN CHOOSE TO MAKE BY BACK SOLDERING CABLE FOR IT C7:

