

AUTOMOBILE SCANNER - REPORT

DATE: Friday, February 10, 2006 09:43 PM

BMW 5xx (E39) 1998

IKE (95-01) Instrument Cluster

Module Info:

BMW Part Number	8381810
Hardware Number	05
Software Number	07
Diagnosis Index	05
Coding Index	11
Bus Index	09
Production Date	17/98
Vehicle VIN	BP24130
Odometer Reading	198892 km

Trouble Codes:

OK No Trouble Codes Stored

Live Parameters Data:

This document was created with Win2PDF available at <http://www.daneprairie.com>.
The unregistered version of Win2PDF is for evaluation or non-commercial use only.